

## List of Tables

Table	Chapter 2	Page
2.2.1	Cephalonia focus towns of the GEER/EERI/ATC reconnaissance and their coordinates.	2-8

Note: No tables are included in Chapters 1, 3, 4, 6, 12 and 13.

<b>Table</b>	<b>Chapter 5</b>	<b>Page</b>
5.1.1	Information on source parameters of strong ( $M \geq 6.0$ ) earthquakes in the area of Cephalonia from 1469 to 1983 (Papazachos and Papazachou, 2003).	5-4
5.1.2	Modified Mercalli (MM) intensities and corresponding effects.	5-5
5.1.3	Venetian documentary sources of information regarding the Ionian islands, available from the State Archives of Venice (ASVe, 1712-1764). Modified from Albini, et al. (1994).	5-7

<b>Table</b>	<b>Chapter 7</b>	<b>Page</b>
7.1.1	Accelerographic stations and ground motion parameters within epicentral distances of 200 km from 1st event (1/26/14, $M_w$ 6.1). Station location, code, owner, geographical coordinates, epicentral and hypocentral distances, azimuth and PGA (cm/s <sup>2</sup> ) for N/L, E/T, Z/V components.	7-6
7.1.2	Highest PGA values and their components recorded during the 1 <sup>st</sup> event at stations ARG2, VSK1, LXRБ, SMHA at epicentral distances of 13, 34, 10, 29 km, respectively.	7-8

<b>Table</b>	<b>Chapter 8</b>	<b>Page</b>
8.1.1	Eurocode EC-8 and ASCE7-05 site classification.	8-13

<b>Table</b>	<b>Chapter 9</b>	<b>Page</b>
9.3.1	Summary of statistics from cemeteries: Entries 1 through 17 are in Paliki peninsula (west part of Cephalonia), ordered from North to South. Entries 18 to 26 are on the main (east) part of the island. Light red indicates toppling rate over 65%; light yellow from 30-65%; and light green less than 30%. Generalized geologic setting: A = Conglomerate, sandstone and limestone and B = Conglomerate and brecciated limestone with marls.	9-31

<b>Table</b>	<b>Chapter 10</b>	<b>Page</b>
10.1.1	Potable water pipe network material and length in the town of Lixouri.	10-5

<b>Table</b>	<b>Chapter 11</b>	<b>Page</b>
11.5.1	Eurocode EC-8 and ASCE7-05 ground types and site classification.	11-26
11.7.1	Public reinforced concrete buildings visually inspected during reconnaissance.	11-46
11.7.2	Educational buildings visually inspected during reconnaissance and assessed by O.Σ.K..	11-51
11.8.1	Cephalonia Orthodox Churches, including name, location, century of construction and repair, Category of Load Bearing (LB) system and Degree of Damage (DD) from the 2014 events.	11-56
11.9.1	Nonstructural components damage observations and construction or design deficiencies by Category of components: architectural, building utilities, furniture and contents.	11-64

